


For details on DSS-14 maintenance impact on DOYs 131 and 135 see previous TM map (2006TMMMap135)



139.23:22-01:38 2h16m of realtime 1024bps data plus 19h50m of recorded 512bps data played back
(138.03:31-23:22) at 8kbps was lost due to DSS-14 film height problem, which once again required maintenance personnel on the antenna. Prior to beginning of activity station personnel had declared the antenna "green". DR G106728 refers.